

Product change notification (PCN)

Title / short description	Firmware update - IOL MA8...DI8
Affected article category	Industrial communication technology
Change category	Software modification
Change number	CDN220001-00
Reason for PCN/PDN Revision	

Purpose/objective of the change
Firmware optimization

Detailed description of the change

Various firmware improvements including security enhancements, IODD handling, IODD parsing, etc. The most recent firmware is available in the download center along with the change log detailing the firmware improvements.

Identifying characteristics

The box label version code will be updated to VC 03 and the webmanager will display Application Base 1.6.36 on Firmware page.

Start of Production (SOP)	-	Last Time Delivery (LTD)	-
Effective date (EOP)	2023-12-31	End of Service (EOSR)	-
End of Sales (EOS)	-		

Short-term change (< 6 months) or discontinuation (< 12 months), due to:

- | | | |
|---|---|--|
| ☐ Software / Firmware Bugfix | ☐ Short-term delivery stop by supplier | ☐ Short-term recall by supplier |
| ☐ Force majeure | ☐ Product improvement with customer benefits | |
| ☐ Others | | |

Attachments

- 1072839_03.png
- 1072839_02.png
- Material_list.csv
- PCN-CDN220001-00_DE
- PCN-CDN220001-00_EN

Material list

Item no.	Item Type	Hardware old	Firmware new	Item no.	Substitute item Type
1072838	IOL MA8 PN DI8	01/1.5.28	01/1.6.36		
1072839	IOL MA8 EIP DI8	01/1.5.28	01/1.6.36		



PHOENIX CONTACT GmbH & Co.KG
Flachsmarktstr. 8, D-32825 Blomberg
www.phoenixcontact.com

RoHS



BM:US03



Sno. 0123456789

Date: 2022-01-06



4 055626 766904

Qty.: **1 pcs**

V/C:03

IOL MA8 EIP DI8

Ord.No.: **10 72 83 9**

Made in the U.S.A. with imported components





PHOENIX CONTACT GmbH & Co.KG
Flachsmarktstr. 8, D-32825 Blomberg
www.phoenixcontact.com

RoHS



BM:US03



Sno. 0123456789

Date: 2022-01-06



4 055626 766904

Qty.: **1 pcs**

V/C:02

IOL MA8 EIP DI8

Ord.No.: **10 72 83 9**

Made in the U.S.A. with imported components

