

Product Change Notification

TE Connectivity

Product Change Notification: P-24-025570 PCN Date: 02-JAN-24


TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:

D369 3 Way Panel Mounted Receptacle Part Marking

Description of Changes

From the date that this PCN is issued, the part number marking on the rear housing (rear body) of the 369 3 Way Panel Mounting receptacle connectors will be split over two separate lines. The Date and Cage codes will also be split over two separate lines. See example images attached.



Product improvement. Following the release of PCN P-23-024669 'Replacement tooling and minor component changes', whereby the geometry of the rear housing was updated to optimise its performance, there is less space for part marking in the location specified on the customer drawing, therefore the part marking will be split over two separate lines to maintain legibility. Drawings, connector construction and performance will not change.

	•			_		
Est	ım:	ΣΤΩ	~	ı ıə	TOC	•

Last Order Date (Obsolete Parts Only):	First Date To Ship (Changed Parts Only):			
	02-JAN-2024			
Last Ship Date (Obsolete Parts Only):	Last Date for Mixed Shipments: (Changed Parts Only):			
	No Mixed Shipments			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
YD369-B33- AP400000	NO			"D369-B33-AP4"			
YD369-B33- NP000000	NO			"D369-B33-NP0"			
YD369-B33- NS1-119P	NO			"D369-B33-NS1- 119P"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
YD369-B33- AP400000	NO			"D369-B33-AP4"			
YD369-B33- NP000000	NO			"D369-B33-NP0"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
YD369-B33-	NO			"D369-B33-NS1-			
NS1-119P	NO			119P"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
YD369-B33- NS1-119P	NO			"D369-B33-NS1- 119P"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
YD369-B33- AP400000	NO			"D369-B33-AP4"			
YD369-B33- NP000000	NO			"D369-B33-NP0"			