

Product change notification (PCN)

Title / short description	BL2 BPC 15xx - WLAN adapter change
Affected article category	HMIs and industrial PCs
Change category	Characteristics
Change number	CDR230003_05-00
Reason for PCN/PDN Revision	

Purpose/objective of the change

In order to continue offering WLAN functionality with the BL2 BPC 15xx product family, we have to replace the old WLAN card with a compatible new one.

Detailed description of the change

End of life of current WLAN adapter requires implementation of new WLAN adapter. Systems equipped with the new WLAN adapter will get their systems with the new driver preinstalled.

Identifying characteristics

Increased hardware revision count. Use MS Info to find out what hardware is being used in your system.

Start of Production (SOP)	-	Last Time Delivery (LTD)	-
Effective date (EOP)	2023-08-26	End of Service (EOSR)	-
End of Sales (EOS)	-		

Short-term change (< 6 months) or discontinuation (< 12 months), due to:

- | | | |
|---|--|--|
| ☐ Software / Firmware Bugfix | ☒ Short-term delivery stop by supplier | ☐ Short-term recall by supplier |
| ☐ Force majeure | ☐ Product improvement with customer benefits | |
| ☐ Others | | |

Attachments

- Material_list.csv
- PCN-CDR230003_05-00_DE
- PCN-CDR230003_05-00_EN

Material list

Item no.	Item Type	Hardware / Firmware		Item no.	Substitute item Type
old	new				
1141843	BL2 BPC 1501E-W	05	06		
1141904	BL2 BPC 1501S-W	05	06		
1158231	BL2 BPC 1501E-W-128-W10-T	05	06		
1158248	BL2 BPC 1501S-W	05	06		
1158250	BL2 BPC 1501E-W	05	06		
1158252	BL2 BPC 1501E-W-64-W10	05	06		
1220309	BL2 BPC 1501E-W-128-W10 VD	05	06		
1305860	BL2 BPC 1501E-W-128	05	06		
1158244	BL2 BPC 1501E-W-64-W10-T	05	06		
1158245	BL2 BPC 1501E-W-128-W10	05	06		