




Product Change Notification

Date Issued :	January 02, 2024	PCN Number :	514667
Reason for Change :	Capacity change or tool replacement Change Supplier		
Description of Change :	This notification is to inform you that Molex is expediting capacity tooling and adding a second source to increase output.		
Assessment of Change :	No change to parts - Form/Fit/Function		
Planned Implementation Date :	July 02, 2024		
Customer Sample Availability Date:	May 29, 2024		
Last date to request Samples by Customer : February 29, 2024			
Please note if Samples are not requested as per Customer Samples Request date, it may take additional 4-6 weeks to arrange Samples.			
Traceability Code Markings / Date :	Cavity identification		

Before Picture

Impacted Products Pictures

DURACLIK NEW 5.0 PITCH WB
CONN. REC. 5WAY HSG



DURACLIK NEW 5.0 PITCH WB
CONN. REC. 5WAY ISL Retainer

After Picture

Overview

- First, due to OEM increase in product, we are experiencing extremely high demand beyond our capacity to respond within lead time. Molex is expediting capacity tooling to increase output.
- Second, with unstable resin supplying, Molex will have second source resin to avoid future shortage risk.
- Product Impact
No impact to fit, form or function
- Part Number Impact
See attached impacted parts list
- Qualification Reports and samples available upon request after the date shown above

RELEASED

You may address inquiries regarding this PCN by clicking on the below link
mailto:pcn_coordinator@molex.com?subject=PCN_Notification:514667
or contact your Local Sales Engineer.

Note: While responding, please retain " PCN Notification : **PCN Notification: 514667** " in the e-mail Subject line for faster response.

Molex, LLC
2222 Wellington Court
Lisle, IL 60532
TEL (800) 786-6539
www.molex.com

PCN No Part List

514667 [0686030460](#)

514667 [5601230500](#)

514667 [5601230501](#)

514667 [5601250500](#)