

Change of epoxy coating - Automotive leaded MLCC (A...V and A...R and A...P series)

For further information, please contact your regional Vishay office.

CONTACT INFORMATION

Americas

Mark Walsh
One Greenwich Place
-
Shelton United States 06484
Phone: 978-474-4254
Fax:
-

Europe

Dr. Florian Weyland
Dr.-Felix-Zandman-Platz 1
-
Selb Germany 95100
Phone: +49-9287-71-2787
Fax:
-

Asia

Boonhooi Tan
37A Tampines St. 92 #07-00
-
Singapore Singapore 528886
Phone: +65-6780-7759
Fax:
-

Description of Change: We will change the epoxy coating of the automotive leaded MLCC A...V and A...R and A...P series. Parts with new epoxy coating will be sent starting April 2025. The color of the epoxy will change from yellow to blue. There will be no change in form/fit/function.

Reason for Change: Obsolescence of the current epoxy from April 2025 on.

Expected Influence on Quality/Reliability/Performance: Quality/Reliability/Performance will stay the same - no influence

Part Numbers/Series/Families Affected: Please see materials list on the succeeding page.

Vishay Brand(S): Vishay BCcomponents

Time Schedule:

Start Shipment Date: Mon Apr 28, 2025

Sample Availability: on request

Product Identification: By series name (A...V and A...R and A...P series)

Qualification Data: on request

This PCN is considered approved, without further notification, unless we receive specific customer concerns before Wed Feb 21, 2024 or as specified by contract.

Issued By: Florian Weyland, florian.veyland@vishay.com



The DNA of tech.™

Product Change Notification



Product Group: CC/Mon Jan 22, 2024/PCN-CC-00004-2024-REV-0

A101J15C0GF5TAAV	A101J15C0GF5UAAP	A101J15C0GH5TAAR	A102J15C0GF5UAAP	A102K15X7RF5TAAR
A102K15X7RF5UAAP	A102K15X7RH5TAAR	A102K15X7RK5UAAV	A102K15X7RK5UAAV0	A103K15X7RF5TAAV
A103K15X7RK5TAAR	A103K15X7RK5TAAV	A103K15X7RK5UAAV	A103K15X7RK5UAAV0	A104K15X7RF5TAAR
A104K15X7RF5TAAV	A104K15X7RF5UAAP	A104K15X7RF5UAAV	A104K15X7RH5TAAR	A104K15X7RH5TAAV
A104K15X7RH5UAAP	A104K20X7RH5TAAV	A104K20X7RK5UAAP	A104M15X7RF5TAAR	A104M20X8RF5TAAV
A105K20X7RF5TAAV	A105K20X7RF5UAAP	A181K15C0GK5TAAV	A222K15X7RF5UAAP	A222K15X7RK5UAAP
A223K15X7RF5UAAP	A224K20X7RF5UAAP	A333K15X7RH5UAAP	A333K20X7RK5UAAP	A334K20X7RF5UAAR
A471K15X7RF5UAAP	A472J20C0GK5UAAP	A472K15X7RF5TAAR	A472K15X7RF5TAAV	A472K15X7RF5UAAP
A472K15X7RH5TAAR	A472K15X7RH5TAAV	A472K15X7RK5TAAV	A473K15X7RF5TAAR	A473K15X7RF5UAAP
A474K20X7RF5UAAP				