

Product Advisory

Issue Date: Jan 25, 2024

Change Type:

Support for Dual Rate Transceivers

Parts Affected:

Part Number	Current Revision	Updated Revision
BCM957504-N425G	029	030

Description of Change:

Updating the BCM957505-N425G to support dual rate transceivers.

Reason for Change:

This change enables customers to support dual rate transceivers.

Effect of Change on Fit, Form, Function, Quality, or Reliability:

The adapter specification remains the same. Customers planning to use dual-rate transceivers should use firmware release 2.18 or more recent. Broadcom recommends using the latest available firmware.

Effective Date of Change:

Product shipments will begin after March 1, 2024 as revision 030.