

Product discontinuation notification (PDN)

Title / short description	Discontinuation of the MXK 4 product family
Affected article category	Terminal blocks
Change category	Discontinuation
Change number	IBE240001-00
Reason for PCN/PDN Revision	

Purpose/objective of the change

Discontinuation as the result of a portfolio revision

Detailed description of the change

Discontinuation due to portfolio streamlining

Identifying characteristics

See attached item list for discontinued items

Start of Production (SOP)	-	Last Time Delivery (LTD)	2025-05-31
Effective date (EOP)	2025-02-28	End of Service (EOSR)	-
End of Sales (EOS)	2025-02-28		

Short-term change (< 6 months) or discontinuation (< 12 months), due to:

- | | | |
|---|---|--|
| ☐ Software / Firmware Bugfix | ☐ Short-term delivery stop by supplier | ☐ Short-term recall by supplier |
| ☐ Force majeure | ☐ Product improvement with customer benefits | |
| ☐ Others | | |

Attachments

- Material_list.csv
- PDN-IBE240001-00_DE
- PDN-IBE240001-00_EN

Material list

Item no.	Item Type	Hardware old	Firmware new	Item no.	Substitute item Type
0561002	MXK 4			3248035	MUT 4
0561028	MXK 4 BU			3248036	MUT 4 BU
0561015	D-MXK 4			3248033	D-MUT 2,5/4