



TE Connectivity

Product Change Notification: P-24-025762 PCN Date: 19-FEB-24

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:

CAGE ASSEMBLY AND LIGHT PIPE ASSEMBLY, 1X4, OSFP

Description of Changes

Duplication of manufacturing capabilities. The following Part Numbers that are currently manufactured at the Guangdong facility, may also be sourced from Malaysia, Johor facility. The parts produced in the new location will have the letters JH" after the existing date code numbers. The parts that are produced in the existing location will have the letters "GD" after the existing date code numbers. Apart from this change, the products manufactured at both locations will be the same and thus retain the current same part number.

Other attachments:

OSFP Cage duplication plan in Malaysia Johor

Reason for Changes:

Dear Customer, In line with TE Connectivity's dedication to providing excellent customer service and delivery, we are updating our business continuity plans to include geodiverse dual-sourcing for select parts. The dual-sourcing is executed by following a strict procedure, which guarantees no unwarranted influence on the quality, ability to supply, and form-fit-function of the concerned products. The new manufacturing location is under a certified quality management system according to the standard industry requirements. Based on our specifications, an internal release will be executed before any parts are delivered, which guarantees the product performance.

Estimated Dates:

Last Order Date (Obsolete Parts Only):	First Date To Ship (Changed Parts Only):
	20-MAY-2024
Last Ship Date (Obsolete Parts Only):	Last Date for Mixed Shipments: (Changed Parts Only):
	No Mixed Shipments

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<u>2338495-3</u>	NO						
<u>2338495-5</u>	NO						

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
2338495-3	NO						
<u>2338495-5</u>	NO						

Part Number(s) being Modified

	Part Discontinued per		Customer Part	Alias Part	Substitute Part	Substitute Alias Part	Description Of
Number	PCN	Drawing	Number	Number(s)	Number	Number(s)	Difference
<u>2338495-3</u>	NO						
<u>2338495-5</u>	NO						

Details of Duplication of OSFP Cage In Malaysia

15 Jan 2024

=TE


EVERY CONNECTION COUNTS

Details of Duplication of OSFP Cage in Malaysia



Components level:

6 sets component tooling duplicated in Malaysia



Component	Tooling Number
Separators die	11-1981953
Top Cage die	11-1981954
Bottom Cage die	11-1981955
EMI Spring die	11-1981956
EMI Spring die	11-1981957
Lightpipe bracket die	11-1981958

Component	Tooling Number	Cavity number
Fiber mold	21-1977656	A,B,C,D
Organizer mold	21-1977655	A,B,C,D

Cage level:

Move 1 cage Assy line to Malaysia

Cage Assembly	Migration	
Line 3	Existing cage Assy line	

Date Code Display Change



To distinguish the manufacture location, the date code printing content will be changed: Add manufacture code after product and label D/C printing content.

Example:

Date code change from YYWWD to YYWWDGD (Manufacture location: Guangdong facility). Date code change from YYWWD to YYWWDJH (Manufacture location: Malaysia Johor facility).

