

Product Change Notification

TE Connectivity

Product Change Notification: P-24-025767 PCN Date: 20-FEB-24

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:
Automotive High Current Relays

Description of Changes

This Product Change Notification (PCN) is to inform about HCR core notching improvement (from manual to automatic press) used to manufacture below listed PNs according to VDA Trigger No 19 The change has no impact to form fit function TE Change process follows a strict procedure which fully maintains quality and ability to supply Internal release process is ensured by TE. Validation will be initiated and completed according to project plan, as soon as samples are available. Traceability of change is ensured by TE. This is an informational PCN and no formal PPAP will be submitted. Please provide your statement to this PCN within 2 weeks after receiving of it.

Reason for Changes:					
Product improvement. As a result of a thorough analysis of demand picture	Product improvement. As a result of a thorough analysis of demand picture matching our customer needs we are going to optimize production for affected PN/s.				
Estimated Dates:					
Last Order Date (Obsolete Parts Only): First Date To Ship (Changed Parts Only):					
04-MAR-2024					
Last Ship Date (Obsolete Parts Only):	Last Date for Mixed Shipments: (Changed Parts Only):				
	06-SEP-2024				

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<u>1-1393315-1</u>	NO			"V23132B2002B200"			
<u>1-1414632-0</u>	NO			"V23132-B2002-X025"			
<u>1393315-9</u>	NO			"V23132B2002A200"			
2-1414939-2	NO			"V23132A2001B200-EV- USBX"			
<u>5-1414968-1</u>	NO			"V23132B2002B200-EV- USBX"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<u>2-1414939-</u> <u>2</u>	NO			"V23132A2001B200-EV- USBX"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<u>1-1393315-</u> <u>1</u>	NO			"V23132B2002B200"			
1-1414632- 0	NO			"V23132-B2002-X025"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<u>1393315-9</u>	NO			"V23132B2002A200"			
<u>2-1414939-</u> <u>2</u>	NO			"V23132A2001B200-EV- USBX"			
5-1414968- 1	NO			"V23132B2002B200-EV- USBX"			