

Product discontinuation notification (PDN)

Title / short description Discontinuation of the RBO*-F (flange) item and some of the items/ accessories from the range of terminal blocks.

Affected article category Terminal blocks

Change category Discontinuation

Change number IBE230016-00

Reason for PCN/PDN Revision

Purpose/objective of the change

Discontinuation due to portfolio optimization

Detailed description of the change

Discontinuation due to availability of alternative products

Identifying characteristics

See item list

Start of Production (SOP)	-	Last Time Delivery (LTD)	2025-05-31
Effective date (EOP)	2025-02-28	End of Service (EOSR)	-
End of Sales (EOS)	2025-02-28		

Short-term change (< 6 months) or discontinuation (< 12 months), due to:

- | | | |
|---|---|--|
| ☐ Software / Firmware Bugfix | ☐ Short-term delivery stop by supplier | ☐ Short-term recall by supplier |
| ☐ Force majeure | ☐ Product improvement with customer benefits | |
| ☐ Others | | |

Attachments

- Material_list.csv
- PDN-IBE230016-00_DE
- PDN-IBE230016-00_EN

Material list

Item no.	Item Type	Hardware / Firmware		Item no.	Substitute item Type
0713122	OTTA 25 M6 PH3			0790491	OTTA 25-M6
1110385	RBO 6-2L/6				
3049819	BE-RT 3/5				
3049916	BE-RT 8				
3058062	RBO 5-F			3058059	RBO 5
3058169	RBO 5-T-F			3058114	RBO 5-T
3058237	RBO 5-F/4			3058059	RBO 5
3058240	RBO 5-F/6			3058059	RBO 5
3058253	RBO 5-F/8			3058059	RBO 5
3059252	RBO 5-F/12			3058059	RBO 5
3075935	RBO 6-F			3075896	RBO 6
3076061	RBO 12-4L-HC			3247986	RBO 12-HC
3076167	RBO 8-3L/N/FE-HC			3247973	RBO 8-HC
3076277	RBO 16-3L/N			3244630	RBO 16
3076280	RBO 8-3L/N/FE			3213137	RBO 8
3213108	D-RSC 6-F				