

PRODUCT CHANGE NOTIFICATION

Date Issued: February 23rd, 2024

Product Identification: Cinch / Dura-Con Jumpers

PCN Number: PCN-####

Reason for Change (s): 2 reasons: 1. The materials used for the insulator on the Cadmium plated shells is Valox, an engineering thermoplastic. 2. The wire color has been changed to 1-10 repeating colors to reduce mis-wiring.

Description of the Change (s): Cinch / Dura-Con is replacing: 1. the DCCM prefix to a DCDM prefix from all Dura-Con Jumper PNs that end with B. 2. The 6E1 description in all PNs is changing to 6E5. These changes do not affect “form, fit, or function”, nor do they affect any other dimensions or electrical parameters of the part.

Planned Timing and Implementation of Change: This change was made beginning in January 2024

Impact on Quality and Reliability: None.

Availability of Qualification Data: None.

Remarks: None.

Signature: Brad Taras, Dura-Con Product Manager



Note: This form should be used if only for advising the customer.

Updated Manufacturer Part Number	Previous Manufacturer Part Number
DCDM9GP6E5-18.0B	DCCM9GP6E1-18.0B
DCDM15GP6E5-18.0B	DCCM15GP6E1-18.0B
DCDM21GP6E5-18.0B	DCCM21GP6E1-18.0B
DCDM25GP6E5-18.0B	DCCM25GP6E1-18.0B
DCDM31GP6E5-18.0B	DCCM31GP6E1-18.0B
DCDM37GP6E5-18.0B	DCCM37GP6E1-18.0B
DCDM51GP6E5-18.0B	DCCM51GP6E1-18.0B
DCDM100GP6E5-18.0B	DCCM100GP6E1-18.0B
DCDM9GS6E5-18.0B	DCCM9GS6E1-18.0B
DCDM15GS6E5-18.0B	DCCM15GS6E1-18.0B
DCDM21GS6E5-18.0B	DCCM21GS6E1-18.0B
DCDM25GS6E5-18.0B	DCCM25GS6E1-18.0B
DCDM31GS6E5-18.0B	DCCM31GS6E1-18.0B
DCDM37GS6E5-18.0B	DCCM37GS6E1-18.0B
DCDM51GS6E5-18.0B	DCCM51GS6E1-18.0B
DCDM100GS6E5-18.0B	DCCM100GS6E1-18.0B
DCDM9PS6E5-18.0B	DCCM9PS6E1-18.0B
DCDM15PS6E5-18.0B	DCCM15PS6E1-18.0B
DCDM21PS6E5-18.0B	DCCM21PS6E1-18.0B
DCDM25PS6E5-18.0B	DCCM25PS6E1-18.0B
DCDM31PS6E5-18.0B	DCCM31PS6E1-18.0B
DCDM37PS6E5-18.0B	DCCM37PS6E1-18.0B
DCDM51PS6E5-18.0B	DCCM51PS6E1-18.0B
DCDM100PS6E5-18.0B	DCCM100PS6E1-18.0B
DCCM9GP6E5-18.0BN	DCCM9GP6E1-18.0BN
DCCM15GP6E5-18.0BN	DCCM15GP6E1-18.0BN
DCCM21GP6E5-18.0BN	DCCM21GP6E1-18.0BN
DCCM25GP6E5-18.0BN	DCCM25GP6E1-18.0BN
DCCM31GP6E5-18.0BN	DCCM31GP6E1-18.0BN
DCCM37GP6E5-18.0BN	DCCM37GP6E1-18.0BN
DCCM51GP6E5-18.0BN	DCCM51GP6E1-18.0BN
DCCM100GP6E5-18.0BN	DCCM100GP6E1-18.0BN
DCCM9GS6E5-18.0BN	DCCM9GS6E1-18.0BN
DCCM15GS6E5-18.0BN	DCCM15GS6E1-18.0BN
DCCM21GS6E5-18.0BN	DCCM21GS6E1-18.0BN
DCCM25GS6E5-18.0BN	DCCM25GS6E1-18.0BN
DCCM31GS6E5-18.0BN	DCCM31GS6E1-18.0BN
DCCM37GS6E5-18.0BN	DCCM37GS6E1-18.0BN
DCCM51GS6E5-18.0BN	DCCM51GS6E1-18.0BN
DCCM100GS6E5-18.0BN	DCCM100GS6E1-18.0BN
DCCM9PS6E5-18.0BN	DCCM9PS6E1-18.0BN
DCCM15PS6E5-18.0BN	DCCM15PS6E1-18.0BN
DCCM21PS6E5-18.0BN	DCCM21PS6E1-18.0BN

DCCM25PS6E5-18.0BN	DCCM25PS6E1-18.0BN
DCCM31PS6E5-18.0BN	DCCM31PS6E1-18.0BN
DCCM37PS6E5-18.0BN	DCCM37PS6E1-18.0BN
DCCM51PS6E5-18.0BN	DCCM51PS6E1-18.0BN
DCCM100PS6E5-18.0BN	DCCM100PS6E1-18.0BN