



Product Change Notification / DSNO-22LQSN443

Date:

29-Feb-2024

Product Category:

Ethernet PHYs

PCN Type:

End of Life

Notification Subject:

eSign #EOL0000108: End of Life (EOL) of LAN8670C1-E/LMXVAO, LAN8670C1T-E/LMXVAO, LAN8671C1-E/U3BVAO, LAN8671C1T-E/U3BVAO, LAN8672C1-E/LNXVAO, LAN8672C1T-E/LNXVAO, LAN8670C1-E/LMX, LAN8670C1T-E/LMX, LAN8671C1-E/U3B, LAN8671C1T-E/U3B, LAN8672C1-E/LNX and LAN8672C1T-E/LNX catalog part numbers (CPN).

Affected CPNs:

[DSNO-22LQSN443_Affected_CPN_02292024.pdf](#)

[DSNO-22LQSN443_Affected_CPN_02292024.csv](#)

Notification Text:

PCN Status:End of Life (EOL) Notification

Microchip Parts Affected:Please open one of the files found in the Affected CPNs section.

The list of affected CPNs with its corresponding replacement parts (if applicable) can be found on the attachments field labeled as PCN_#_Suggested Replacements.

NOTE: For your convenience Microchip includes identical files in two formats (.pdf and .xls).

EOL Description:The LAN8670C1-E/LMXVAO, LAN8670C1T-E/LMXVAO, LAN8671C1-E/U3BVAO, LAN8671C1T-E/U3BVAO, LAN8672C1-E/LNXVAO, LAN8672C1T-E/LNXVAO, LAN8670C1-E/LMX, LAN8670C1T-E/LMX, LAN8671C1-E/U3B, LAN8671C1T-E/U3B, LAN8672C1-E/LNX and LAN8672C1T-E/LNX catalog part numbers (CPN) will be moving to End of Life (EOL) status effective today. These catalog part numbers will no longer be offered after August 29, 2024. Please review the attached parts affected list below for details about replacement parts if applicable.

Note: If replacement parts are not listed in the attached list please contact your **Local Sales Representative**

Reason for EOL:No longer have manufacturing support for the CPN listed in the attachment.

Estimated Effective Dates:Customers affected by this EOL notice are advised to place last time buy (LTB) orders as follows:

Last date for bookings (LTB): May 29, 2024

Last date for shipments (LTS): August 29, 2024

Revision History:February 29, 2024: Issued EOL Notification.

Attachments:

[PCN_DSNO-22LQSN443_Suggested Replacement.pdf](#)

[PCN_DSNO-22LQSN443_Suggested Replacement.xlsx](#)

Please contact your local **Microchip sales office** with questions or concerns regarding this notification.

Terms and Conditions:

If you wish to receive Microchip PCNs via email please register for our PCN email service at our **PCN home page** select register then fill in the required fields. You will find instructions about registering for Microchips PCN email service in the **PCN FAQ** section.

If you wish to change your PCN profile, including opt out, please go to the **PCN home page** select login and sign into your myMicrochip account. Select a profile option from the left navigation bar and make the applicable selections.

DSNO-22LQSN443 - eSign #EOL0000108: End of Life (EOL) of LAN8670C1-E/LMXVAO, LAN8670C1T-E/LMXVAO, LAN8671C1-E/U3BVAO, LAN8671C1T-E/U3BVAO, LAN8672C1-E/LNXVAO, LAN8672C1T-E/LNXVAO, LAN8670C1-E/LMX, LAN8670C1T-E/LMX, LAN8671C1-E/U3B, LAN8671C1T-E/U3B, LAN8672C1-E/LNX and LAN8672C1T-E/LNX catalog part numbers (CPN).

Affected Catalog Part Numbers (CPN)

- LAN8670C1-E/LMXVAO
- LAN8670C1T-E/LMXVAO
- LAN8671C1-E/U3BVAO
- LAN8671C1T-E/U3BVAO
- LAN8672C1-E/LNXVAO
- LAN8672C1T-E/LNXVAO
- LAN8670C1-E/LMX
- LAN8670C1T-E/LMX
- LAN8671C1-E/U3B
- LAN8671C1T-E/U3B
- LAN8672C1-E/LNX
- LAN8672C1T-E/LNX