



March 20, 2024

Dear Valued Partner,

Semtech Corporation has determined one of our subcontractors was incorrectly taping certain products using a 12mm tape width instead of Semtech's standard 16mm width tape.

The following part numbers are affected with batch numbers between 442000 and 463000.

Part Number
GS12081-INTE3
GS12150-INTE3
GS12181-INTE3
GS12182-INTE3
GS12281-INTE3
GS12281-INTE3Z
GS3281-INTE3
GS3281-INTE3Z

Please see the next page for summary of batch numbers and their part numbers.

Customers are advised to adjust their tape feeders to process the smaller tape width.

There are no other impacts to form, fit, and function of the affected devices.

For any further assistance, please contact your Semtech Sales Representative.

A handwritten signature in black ink, appearing to read "L. Blanco", with a horizontal line drawn underneath it.

Luis Blanco
VP Quality Engineering and Technology
Semtech Corporation



No.	Batch No.	Part Number	Part Number
1	442472	GS12281-INTE3Z	
2	442473	GS12281-INTE3Z	
3	445550	GS12281-INTE3	GS12281-INTE3Z
4	446926	GS12150-INTE3	
5	446927	GS12150-INTE3	
6	447049	GS12281-INTE3Z	
7	447052	GS12182-INTE3	
8	447053	GS12081-INTE3	
9	447767	GS12281-INTE3	
10	448148	GS12281-INTE3	
11	448149	GS12150-INTE3	
12	451020	GS12281-INTE3	
13	453115	GS12150-INTE3	
14	453117	GS12182-INTE3	
15	453119	GS12281-INTE3Z	
16	453576	GS12181-INTE3	
17	453577	GS12182-INTE3	
18	453578	GS3281-INTE3	
19	454571	GS12281-INTE3Z	
20	454573	GS12182-INTE3	
21	454574	GS12150-INTE3	
22	454576	GS3281-INTE3	
23	455511	GS12182-INTE3	
24	455512	GS12150-INTE3	
25	455513	GS3281-INTE3	
26	456252	GS12181-INTE3	
27	456253	GS12150-INTE3	
28	456907	GS12281-INTE3	
29	456908	GS12281-INTE3	
30	457576	GS12182-INTE3	
31	461016	GS12281-INTE3	
32	461745	GS12281-INTE3	
33	461746	GS12281-INTE3	
34	462226	GS12281-INTE3	