

**Product Discontinuation Notice**

Issue Date  
March 1, 2024

**Product Discontinuation**

Limit Switches

**D4A series some items**

**D4C series some items**

**D4E series some items**

**D4F-120-10R**

**D4N series some items**

**D4N-R series some items**

**SC-3FD**

**SHL-W2155-L4MR VCTF5M**

**WL series some items**

**ZC series some item**

**ZE series some item**



**Recommended Replacement**

**No recommended replacement**

**[ Final order entry date ]**

The end of March, 2025

**[ Date of The Last Shipping ]**

The end of June, 2025

**[ Product Discontinuation and recommended replacement ]**

Product discontinuation	Recommended replacement
D4A-1E11N	No recommended replacement
D4A-4M17N	No recommended replacement
D4C-1933	No recommended replacement
D4C-2441	No recommended replacement
D4C-3850	No recommended replacement
D4C-5242	No recommended replacement
D4E-1C23N 1M	No recommended replacement
D4E-2C24L2N	No recommended replacement
D4F-120-10R	No recommended replacement
D4N-1B72	No recommended replacement
D4N-1E22	No recommended replacement
D4N-4B25	No recommended replacement
D4N-4C25-NPT	No recommended replacement
D4N-4CRE	No recommended replacement
D4N-4DRE	No recommended replacement
D4N-4E31	No recommended replacement
D4N-4ELE	No recommended replacement
D4N-8D72	No recommended replacement
D4N-9E32	No recommended replacement
D4N-2B72R	No recommended replacement
D4N-2D2HR	No recommended replacement

<b>Product discontinuation</b>	<b>Recommended replacement</b>
D4N-8A72R	No recommended replacement
SC-3FD	No recommended replacement
SHL-W2155-L4MR VCTF5M	No recommended replacement
WL-1A207	No recommended replacement
WL-1A600S	No recommended replacement
WL01CA2-RP55	No recommended replacement
WL01H12-0P1139-CN1 3D	No recommended replacement
WL01NJ-G1LD	No recommended replacement
WLCA12-TSLD	No recommended replacement
WLCA2-255Y	No recommended replacement
WLCA2-28	No recommended replacement
WLCA2-55LD-DK1EJ03	No recommended replacement
WLCA2-8TC	No recommended replacement
WLCA2-LD-AGJ03	No recommended replacement
WLCA32-41139 VCT 5M	No recommended replacement
WLCL-139 2M	No recommended replacement
WLCL-2NTS	No recommended replacement
WLCL-P1140 2M	No recommended replacement
WLD-LR-DHJS03-A	No recommended replacement
WLD2-RP40	No recommended replacement
WLH2-RP60LD3 5M	No recommended replacement
WLNJ-2G1 CE	No recommended replacement
WLRH2-RP	No recommended replacement
WLS2-RP139 5M	No recommended replacement
WL-2H-N(FOR WLRG2-N)	No recommended replacement
ZC-Q55S	No recommended replacement
ZC-W2155-ML VCT 3M	No recommended replacement
ZC-W2155-MR VCT 3M	No recommended replacement
DZV2-NA2-2TC1	No recommended replacement
ZV-Q21-2S	No recommended replacement

Specifications and prices in this product news are as of the issue date and are subject to change without notice. Only main changes in specifications are described in this document. Please be sure to read the relevant catalogs, datasheets, product specifications, instructions, and manuals for precautions and necessary information when using products.