

Document Number: D07512-A-A2127

Date: Apr. 01, 2024

Request for approval for alternative production at Yokaichi factory due to impact of earthquake to Anamizu factory

Winding type Common mode choke coil DLW5A/DLW5B series

Chip inductor LQH2HNH_03, LQH2HPN/Z/H_GR, LQH2HPZ_JR, LQH3NPZ/H_23, LQH3NPN/Z/H_ME, LQH43CN_03, LQH43NN/Z/H_03, LQH43PN/Z/H/B_26 series

Dear, Valued Customer

Thank you very much for your great and continued support for business with Murata.

This is the official notification that some of our products detailed below.

Please review this, and accept in writing.

Your understanding and support are highly appreciated.

1. Product Type and Customer/Murata Part Numbers:

Product Type: DLW5A/DLW5B series

LQH2HNH 03, LQH2HPN/Z/H GR, LQH2HPZ JR, LQH32NZ/H 23, LQH3NPN/Z/H ME,

LQH43CN 03, LQH43NN/Z/H 03, LQH43PN/Z/H/B 26 series

Please refer to the attached documents for Part Numbers' information.

2. Background/Request:

These series are produced by our company, Anamizu Murata Manufacturing Co., Ltd. (Anamizu Factory).

Anamizu factory was affected by the 2024 Noto Peninsula earthquake that occurred on January 1, 2024.

At the present time, production has been suspended, but we are working on the recovery and earliest schedule will be after May.

Therefore, we will commence alternative production at Yokaichi Factory (*1) urgently. Please approve the temporary supply of Yokaichi Factory products until Anamizu Factory is recommence operation.

Please note that there are no changes to the 4M (Man, Machine, Material, Method).(*2) If you agree to supply(*3) products produced at Yokaichi factory(*2), please sign and reply to us on separate sheet.

- *1: Murata Manufacturing Company, Ltd. Yokaichi Factory
- *2: Production will be carried out at Yokaichi factory using the equipment and production operator from Anamizu Factory.
- *3: Supply quantity and timing cannot be guaranteed.

3. Approval Due:

May, 17, 2024

4. Contact Window:

Should you have any questions or concerns, please contact Murata Sales, Representative, or Distributor in your area.

Truly Yours. Thank you.

Murata Manufacturing, Co., Ltd.

Marketing & Promotion Department EMI Filter Division
Hiromi Nagasaka



Confirmation Letter

Murata Manufacturing, Co., Ltd.

Request for approval for alternative production at Yokaichi factory due to impact of earthquake to Anamizu factory

	of the following products, DLW5A/DLW5B series	accepted.	not accepted.
	LQH2HNH_03, LQH2HPN/Z/H_GF LQH43CN_03, LQH43NN/Z/H_03,		
Comments	, Questions, etc.		
Signature Date: (MM,	DD, YYYY)		
Title:			
Name:			

Murata Part Number

DLW5ATH111TQ2L

DLW5ATH112MQ2L

DLW5ATH151MQ2L

DLW5ATH231TQ2L

DLW5ATH331MQ2L

DLW5ATH401TQ2L

DLW5ATH450TQ2L

DLW5ATH500MQ2L

DLW5ATH501MQ2L

DLW5ATH501TQ2L

DLW5ATN111SQ2L

DLW5ATN111TQ2L

DLW5ATN111Q2L

DLW5ATN151MQ2L

DLW5ATN231TQ2L

DLW5ATN2772SQ2L

DLW5ATN331MQ2L

DLW5ATN401SQ2L

DEVIO/(1114-010-02-1

DLW5ATN500MQ2L

DLW5ATN501MQ2L

DLW5ATN501TQ2L

DLW5ATN851SQ2L

DLW5ATZ112MQ2L

DLW5ATZ450TQ2L

DLW5BSM102SQ2L

DLW5BSM152SQ2L

DLW5BSM191SQ2L

DLW5BSM302SQ2L DLW5BSM351SQ2L

DLW5BSM501TQ2L

DEWODOWOUTQZE

DLW5BSM601TQ2L

DLW5BSM801TQ2L

DLW5BSZ601TQ2L

DLW5BSZ801TQ2L

DLW5BTH101TQ2L

DLW5BTH102TQ2L

DLW5BTH142TQ2L

DLW5BTH251TQ2L

DLW5BTH501TQ2L DLW5BTM101SQ2L

DI WEDTMANATON

DLW5BTM101TQ2L

DLW5BTM102SQ2L DLW5BTM102TQ2K

DLW5BTM102TQ2L

DLW5BTM142SQ2L

DEWSBTW1423Q2L

DLW5BTM142TQ2L

DLW5BTM251SQ2L

DLW5BTM251TQ2L

DLW5BTM501SQ2L

DLW5BTM501TQ2L DLW5BTZ142TQ2L

DLW5BTZ251TQ2L

LQH2HNH100J03L

- LQH2HNH101J03L
- LQH2HNH120J03L
- LQH2HNH150J03L
- LQH2HNH180J03L
- LQH2HNH1R0M03L
- LQH2HNH1R2K03L
- LQH2HNH1R5K03L
- LQH2HNH1R8J03L
- LQH2HNH220J03L
- LQH2HNH270J03L LQH2HNH2R2J03L
- LQH2HNH2R7K03L
- LQH2HNH330J03L
- LQH2HNH390J03L
- LQH2HNH3R3J03L
- LQH2HNH3R9J03L
- LQH2HNH470J03L
- LQH2HNH4R7J03L
- LQH2HNH560J03L
- LQH2HNH5R6J03L
- LQH2HNH680J03L
- LQH2HNH6R8J03L
- LQH2HNH820J03L
- LQH2HNH8R2J03L
- LQH2HNHR56K03L
- LQH2HNHR68K03L
- LQH2HNHR82K03L
- LQH2HPH100MGRL
- LQH2HPH150MGRL
- LQH2HPH1R0MGRL
- LQH2HPH1R5MGRL
- LQH2HPH220MGRL
- LQH2HPH2R2MGRL LQH2HPH3R3MGRL
- LQH2HPH4R7MGRL
- LQH2HPH6R8MGRL
- LQH2HPHR47MGRL
- LQH2HPHR68MGRL
- LQH2HPN100MGRL
- LQH2HPN101MGRL
- LQH2HPN1R0MGRL
- LQH2HPN1R5MGRL
- LQH2HPN220MGRL
- LQH2HPN2R2MGRL
- LQH2HPN3R3MGRL
- LQH2HPN4R7MGRL
- LQH2HPN6R8MGRL
- LQH2HPNR47MGRL LQH2HPNR68MGRL
- LQH2HPZ100MGRL
- LQH2HPZ100MJRL LQH2HPZ150MGRL
- LQH2HPZ150MJRL
- LQH2HPZ1R0MGRL
- LQH2HPZ1R0NJRL
- LQH2HPZ1R2NJRL
- LQH2HPZ1R5MGRL

- LQH2HPZ1R5NJRL
- LQH2HPZ220MGRL
- LQH2HPZ220MJRL
- LQH2HPZ2R2MGRL
- LQH2HPZ2R2MJRL
- LQH2HPZ3R3MGRL
- LQH2HPZ3R3MJRL
- LQH2HPZ4R7MGRL
- LOUISIUDZADZNAJDI
- LQH2HPZ4R7MJRL
- LQH2HPZ6R8MGRL
- LQH2HPZ6R8MJRL
- LQH2HPZR47NJRL LQH2HPZR68MGRL
- LQH32NH100J23L
- LQH32NH101J23L
- LQH32NH120J23L
- 24110214111200201
- LQH32NH121J23L
- LQH32NH150J23L LQH32NH151J23L
- LQH32NH180J23L
- LQH32NH181J23L
- LQH32NH1R0M23L
- LQH32NH1R5J23L
- LQH32NH220J23L
- LQH32NH221J23L
- LQH32NH270J23L
- LQH32NH271J23L
- LQH32NH2R2J23L
- LQH32NH2R7J23L
- LQH32NH331J23L
- LQH32NH391J23L
- LQH32NH3R3J23L
- LQH32NH3R9J23L
- LQH32NH470J23L
- LQH32NH471J23L
- LQH32NH4R7J23L LQH32NH560J23L
- LQH32NH561J23L
- LQH32NH5R6J23L
- LQH32NH680J23L
- LQH32NH6R8J23L
- LQH32NH820J23L
- LQH32NH8R2J23L
- LQH32NZ100J23L
- LQH32NZ101J23L
- LQH32NZ120J23L
- LQH32NZ121J23L
- LQH32NZ150J23L
- LQH32NZ151J23L
- LQH32NZ180J23L
- LQH32NZ181J23L
- LQH32NZ1R0K23L
- LQH32NZ1R2K23L
- LQH32NZ1R5K23L
- LQH32NZ1R8K23L
- LQH32NZ220J23L LQH32NZ221J23L

- LQH32NZ270J23L
- LQH32NZ271J23L
- LQH32NZ2R2K23L
- LQH32NZ2R7K23L
- LQH32NZ330J23L
- LQH32NZ331J23L
- EQ1102112001020E
- LQH32NZ390J23L
- LQH32NZ391J23L
- LQH32NZ3R3K23L
- LQH32NZ3R9K23L
- LQH32NZ470J23L
- LQH32NZ471J23L
- LQH32NZ4R7K23L
- LQH32NZ560J23L
- LQ1102112000020L
- LQH32NZ5R6K23L
- LQH32NZ680J23L
- LQH32NZ6R8K23L
- LQH32NZ820J23L
- LQH32NZ8R2K23L
- LQH3NPH100MMEL
- LQH3NPH101MMEL
- LOUISNIPHIAFONANAFI
- LQH3NPH150MMEL
- LQH3NPH1R0MMEL
- LQH3NPH220MMEL
- LQH3NPH2R2MMEL
- LQH3NPH330MMEL LQH3NPH3R3MMEL
- LQH3NPH470MMEL
- LQH3NPH4R7MMEL
- LQH3NPH560MMEL
- LQH3NPH680MMEL
- LQH3NPH6R8MMEL
- LQH3NPN100MMEL
- LQH3NPN101MMEL
- LQH3NPN150MMEL
- LQH3NPN1R0MMEL
- LQH3NPN220MMEL
- LQH3NPN2R2MMEL
- LQH3NPN330MMEL
- LQH3NPN3R3MMEL
- LQH3NPN470MMEL
- LQH3NPN4R7MMEL
- LQH3NPN560MMEL
- LQH3NPN680MMEL
- LQH3NPN6R8MMEL
- LQH3NPZ100MMEL
- LQH3NPZ101MMEL
- LQH3NPZ150MMEL
- LQH3NPZ1R0MMEL
- LQH3NPZ220MMEL
- LQH3NPZ2R2MMEL
- LQH3NPZ330MMEL
- LQH3NPZ3R3MMEL
- LQH3NPZ470MMEL
- LQH3NPZ4R7MMEL LQH3NPZ6R8MMEL
- LQH43CN100K03L

- LQH43CN101K03L
- LQH43CN150K03L
- LQH43CN151K03L
- LQH43CN1R0M03L
- LQH43CN1R5M03L
- LQH43CN220K03L
- LQH43CN221K03L
- LOUISONEDANIO
- LQH43CN2R2M03L LQH43CN330K03L
- LQH43CN331K03L
- LQH43CN3R3M03L
- EQTI-0011011011001
- LQH43CN470K03L
- LQH43CN471K03L
- LQH43CN4R7M03L
- LQH43CN680K03L
- LQH43CN6R8M03L
- LQH43NH100J03L
- LQH43NH101J03L
- LQH43NH102J03L
- LQH43NH120J03L
- LQH43NH121J03L
- LQH43NH122J03L
- LQH43NH150J03L
- LQH43NH151J03L
- LQH43NH152J03L
- LQH43NH180J03L
- LQH43NH181J03L
- LQH43NH182J03L
- LQH43NH1R0M03L
- LQH43NH1R2K03L
- LQH43NH1R5J03L
- LQH43NH1R8J03L
- LQH43NH220J03L
- LQH43NH221J03L
- LQH43NH222J03L
- LQH43NH270J03L
- LQH43NH271J03L
- LQH43NH2R2J03L
- LQH43NH2R7J03L
- LQH43NH330J03L
- LQH43NH331J03L
- LQH43NH390J03L
- LQH43NH391J03L
- LQH43NH3R3J03L
- LQH43NH3R9J03L
- LQH43NH470J03L
- LQH43NH471J03L
- LQH43NH4R7J03L
- LQH43NH560J03L
- LQH43NH561J03L
- LQH43NH5R6J03L
- LQH43NH680J03L
- LQH43NH681J03L LQH43NH6R8J03L
- LQH43NH820J03L
- LQH43NH821J03L
- LQH43NH8R2J03L

- LQH43NN100J03L
- LQH43NN100K03L
- LQH43NN101J03L
- LQH43NN101K03L
- LQH43NN102J03L
- LQH43NN102K03L
- EQTI45ININTOZINOSE
- LQH43NN120J03L
- LQH43NN120K03L
- LQH43NN121J03L
- LQH43NN121K03L
- LQH43NN122J03L
- LQH43NN122K03L
- LQH43NN150J03L
- LQH43NN150K03L
- LQH43NN151J03L
- LQH43NN151K03L
- LQH43NN152J03L
- LQH43NN152K03L
- LQH43NN180J03L
- LQH43NN180K03L
- LQH43NN181J03L
- LQH43NN181K03L
- LQH43NN182J03L
- LQH43NN182K03L
- LQH43NN1R0M03L
- EQIT-ONITITOMOOL
- LQH43NN1R2M03L
- LQH43NN1R5M03L
- LQH43NN1R8M03L
- LQH43NN220J03L
- LQH43NN220K03L
- LQH43NN221J03L
- LQH43NN221K03L
- LQH43NN222J03L
- LQH43NN222K03L
- LQH43NN242J03L
- LQH43NN242K03L
- LQH43NN270J03L
- LQH43NN270K03L
- LQH43NN271J03L
- LQH43NN271K03L
- LQH43NN2R2M03L
- LQH43NN2R7M03L
- LQH43NN330J03L
- LQH43NN330K03L
- LQH43NN331J03L
- LQH43NN331K03L
- LQH43NN390J03L
- LQH43NN390K03L
- LQH43NN391J03L
- LQH43NN391K03L
- LQH43NN3R3M03L
- LQH43NN3R9M03L
- LQH43NN470J03L
- LQH43NN470K03L LQH43NN471J03L
- LQH43NN471K03L
- LQH43NN4R7K03L

LQH43NN4R7M03L

LQH43NN560J03L

LQH43NN560K03L

LQH43NN561J03L

LQH43NN561K03L

LQH43NN5R6K03L

LQH43NN5R6M03L

LQH43NN680J03L

LQH43NN680K03L

LQH43NN681J03L

20111011110010002

LQH43NN681K03L

LQH43NN6R8M03L

LQH43NN820J03L

LQH43NN820K03L

LQH43NN821J03L

LQH43NN821K03L

LQH43NN8R2K03L

LQH43NN8R2M03L

LQH43PB100M26L

LQH43PB1R0N26L

LQH43PB221M26L

LQH43PH100M26L

LQH43PH101M26L

LQH43PH151M26L

LQH43PH1R0N26L

LQH43PH220M26L

LQH43PH221M26L

LQH43PH2R2M26L

LQH43PH3R3M26L

LQH43PH470M26L

LQH43PH4R7M26L

LQH43PH6R8M26L

LQH43PH8R2M26L LQH43PN100M26L

EQTI45T NTOOMEOL

LQH43PN101M26L

LQH43PN151M26L

LQH43PN1R0N26L

LQH43PN220M26L

LQH43PN221M26L

LQH43PN2R2M26L

LQH43PN3R3M26L

LQH43PN470M26L

LQH43PN4R7M26L

LQH43PN6R8M26L

LQH43PN8R2M26L

LQH43PZ470M26L