

## PRODUCT CHANGE NOTIFICATION

Product Category	COPPER PATCHCORDS				20240326-1	
Product Group		ENTERPRISE CONNECTIVITY				
ISSUE DATE:	26-Mar-24				_	
IMPACTED REGIONS:	✓ NA	✓ EMEA	✓ LATAM	✓ AP	_	
REASON FOR CHANGE:	✓ DISCONT	INUATION				
	OTHER					
DESCRIPTION OF CHANGE:	(Required)					
Panduit is announcing the discontinuation of 5 Zone Cords Parts that have compatible replacements.						
Thank you for your ongo	ing support.	•				

\*Important: A return material authorization (RMA) may be obtained for these affected part numbers and they may be returned up to 60 days after the product discontinuation announcement date if purchased within the last 18 months and subject to the return policy requirements outlined in Panduit's Authorized Distributor Policy. Please contact your local Panduit Customer Experience team if you have any questions.

Year

(YYYY)

2024

Month

(MM)

3

Day

(DD)

26

DATES: DISCONTINUATION AND NEW PRODUCT AVAILABILITY:

**SCHEDULE FOR CHANGE** 

New product sample availability date

IMPACTED PART NUMBERS AND REPLACEMENT PART NUMBERS: (where applicable)								
				Grouping				
				(For				
	Compatibility	Replacement	Replacement	Complex	Discontinuation			
PART NUMBER	Туре	Part 1	Part 2	only)	Date			
SAPRBU100	Compatible	UZPPBU100			24-JUN-2024			
UPLBU50M/N	Direct	UPLBU50M			24-JUN-2024			
UPLBU60M/N	Direct	UPLBU60M			24-JUN-2024			
UXPLWH40M	Compatible	UZPDWH40M			24-JUN-2024			
UZPRBU80	Compatible	UZPPBU80			24-JUN-2024			