



Expertise Applied | Answers Delivered

PRODUCT CHANGE NOTICE

PCN494: Plating Supplier Transition

Issue Date: May 16, 2024

Dear Valued Customer,

This notice is to inform you of a supply chain change affecting select Littelfuse items you have purchased.

Description of the Change:

We will transition the provider of plating processes on the cast components of the attached finished goods from its current supplier to a new supplier who currently provides similar processes on similar products for Littelfuse today. As a part of this resourcing effort, we will change the plating color for some part numbers from platinum gold chromate to a yellow/gold chromate.

Reason for The Change:

We will transition this process as a result of recurring issues with the current supplier, including timely communication, production standards, and continued commercial negotiations.

Effective Date of the Change:

The transition will occur as a running change, effective immediately.

What You Need to Do:

No action is required from you; there will be no change in fit, form, function or visual appearance of these parts.

If you have any questions, please contact your Customer Service or Inside Sales Representative. We appreciate your business and our continued partnership.

Sincerely,

Luisa Cuevas
Associate Product Manager
Littelfuse Commercial Vehicle Products

Part Numbers
880216200
95633-A
95633-A-BX
M-95502
M-95604-01
90030-26
90036-09
90000-01
90020
9216
9216-BX
9216-03
9216-03-BX
9216-03-WBXC
9216-03-WBXP
9216-05
9216-09
9216-10
04982001ZXFC
04982002ZXFC
68166-19
68166-11
68166-12
68166-20
68166-17
68166-14
4112-RC004
4124-RD004
64908-AF
PL-117-AC001
PL-117-GC001
PL-117-RC001
PL-117-RD001
PL-118-AC001
PL-118-AC006
M-754-01
M-754-01-BP
M-755-01
M-755-01-BP
PL-118-GC001
PL-118-GC001-BX
PL-118-GC004
PL-118-RA016
PL-118-RC001
PL-118-RC001-BX
PL-118-RC012

24200
24200-BX
24200-WBXP
882-267-003
FLEC0015Z-0
FLEC0030Z-01
FLEC0021Z-2
FLEC0026Z-01
M-700
M-700-BX
M-711
M-711-BX
M-711-06
M-702
882-267-004
91113-20
91113-19
48161
48161-BX
90068
90066-02
48161
48161-BX
882-267-005
48051
48051-BX
48051
48051-BX
95668-02
90060-05