



Product Change Notification / SYST-05RMFZ673

Date:

06-Jun-2024

Product Category:

Ethernet PHYs

PCN Type:

Document Change

Notification Subject:

LAN8650/1 Silicon Errata and Data Sheet Clarification

Affected CPNs:

[SYST-05RMFZ673_Affected_CPN_06062024.pdf](#)

[SYST-05RMFZ673_Affected_CPN_06062024.csv](#)

Notification Text:

SYST-05RMFZ673

Microchip has released a new Document for the LAN8650/1 Silicon Errata and Data Sheet Clarification of devices. If you are using one of these devices please read the document located at [LAN8650/1 Silicon Errata and Data Sheet Clarification](#).

Notification Status: Final

Description of Change:

- s2, s3: Errata removed
- s9: Errata added
- d1: Data Sheet Clarification added: SPI Operational Characteristics

Impacts to Data Sheet: None

Reason for Change: To Improve Productivity

Change Implementation Status: Complete

Date Document Changes Effective: 06 Jun 2024

NOTE: Please be advised that this is a change to the document only the product has not been changed.

Markings to Distinguish Revised from Unrevised Devices: N/A

Attachments:

LAN8650/1 Silicon Errata and Data Sheet Clarification

Please contact your local **Microchip sales office** with questions or concerns regarding this notification.

Terms and Conditions:

If you wish to receive Microchip PCNs via email please register for our PCN email service at our **PCN home page** select register then fill in the required fields. You will find instructions about registering for Microchips PCN email service in the **PCN FAQ** section.

If you wish to change your PCN profile, including opt out, please go to the **PCN home page** select login and sign into your myMicrochip account. Select a profile option from the left navigation bar and make the applicable selections.

Affected Catalog Part Numbers (CPN)

LAN8650B1-E/LMX
LAN8650B1-E/LMXVAO
LAN8650B1T-E/LMX
LAN8650B1T-E/LMXVAO
LAN8651B1-E/LMX
LAN8651B1-E/LMXVAO
LAN8651B1-E/REL
LAN8651B1T-E/LMX
LAN8651B1T-E/LMXV01
LAN8651B1T-E/LMXVAO