

Product Obsolescence Notification

Issue Date: 07-June-2024

Dear Customer:

Broadcom regrets to announce the obsolescence of the following products due to package material obsolescence and supply.

Broadcom Part Numbers	LTB Date (LTB)	LTS Date (LTS)	MOQ	Suggested Replacement
PEX8604-BA50BC G	12/2/24	6/2/25	3780	None
PEX8604-BA50BI G	12/2/24	6/2/25	3780	None
PEX8606-BA50BC G	12/2/24	6/2/25	3780	PEX8718
PEX8606-BA50BI G	12/2/24	6/2/25	3780	PEX8748
PEX8608-BA50BC G	12/2/24	6/2/25	3780	PEX8764
PEX8609-BA50BC G	12/2/24	6/2/25	3780	None
PEX8609-BA50BI G	12/2/24	6/2/25	3780	None
PEX8613-BA50BC G	12/2/24	6/2/25	2520	PEX8764
PEX8614-BA50BC G	12/2/24	6/2/25	2520	None
PEX8615-BA50BC G	12/2/24	6/2/25	2520	None
PEX8615-BA50BI G	12/2/24	6/2/25	2520	None
PEX8617-BA50BC G	12/2/24	6/2/25	2520	PEX8764
PEX8618-BA50BC G	12/2/24	6/2/25	3024	PEX8714
PEX8619-BA50BC G	12/2/24	6/2/25	3024	PEX8764
PEX8619-BA50BI G	12/2/24	6/2/25	1512	PEX8750

Please provide your Broadcom Sales Office with your lifetime Last Time Buy order requirements (LTB) for the above products no later than the date noted in the above table. These orders are non-cancelable, non-returnable and cannot be rescheduled. Orders received after the Last Time Buy (LTB) order date noted in the above table cannot be accepted.



The last requested delivery date for these orders may not be later than the Last Time Ship (LTS) date noted in the above table. Due to inherent variations in yields, Broadcom reserves the right to ship up to 5% under the original last time buy quantity, and this quantity will fully satisfy Broadcom's obligation to deliver that product under this last time buy agreement.

All last time buy orders must be placed based on Broadcom's minimum order quantity (MOQ) requirements per the above table. All prior commitments regarding Broadcom's minimum order requirements do not apply to last time buy orders. Broadcom reserves the right to limit last time buy quantities based on capacity and material availability.

Note: Please review the data sheets of the suggested replacement parts before selecting one for redesign as they are not pin/package compatible and may not have all the functions of parts being EOLed.

Please contact your Broadcom field sales engineer or Contact Center for any questions or support requirements. Please acknowledge the receipt of the notice within 30 days of delivery. Lack of acknowledgement within 30 days constitutes acceptance of the change per JEDEC J-STD-046.