

**Date: August 13, 2024****To: Coto Distribution Product Manager****RE: RedRock® EOL Notice**

Effective immediately: Please change the status of the following Redrock® part numbers on your website as “End of Life” or “Obsolete”. Coto will no longer be accepting orders for these products.

RR112-1D92-532	RR122-1B13-512	RR122-2E22-511	RR132-1B13-551
RR112-1D93-532	RR122-1B53-511	RR122-2E23-511	RR132-1B13-552
RR112-1G42-532	RR122-1B92-511	RR122-2E32-511	RR132-2E22-551
RR112-1G43-531	RR122-1B92-512	RR122-2E33-511	RR132-2E23-551
RR112-1G43-532	RR122-1B93-511	RR122-3C72-511	RR132-2E32-551
RR122-1A23-511	RR122-1B93-512	RR122-3C72-512	RR132-2E33-551
RR122-1A23-512	RR122-1E73-511	RR122-3C73-512	RR142-1LD2-542
RR122-1A52-511	RR122-1F22-511	RR122-3CU2-515	RR142-1LD2-545
RR122-1A53-511	RR122-1F23-511	RR122-3CU3-515	RR142-1LD3-542
RR122-1B12-511	RR122-2B22-511	RR132-1B12-551	RR142-1LD3-545
RR122-1B13-511	RR122-2B23-511	RR132-1B12-552	

The below RedRock® part numbers are on Runout Status and, while they are not recommended for new designs, they can still be ordered. Please note: All orders are subject to availability and are NCNR.

Available for Order (NCNR)	
RR112-1G42-531	RR122-1E72-511
RR122-1A22-511	RR122-3C62-511
RR122-1A22-512	RR122-3C63-511
RR122-1B12-512	RR122-3C73-511
RR122-1B52-511	

Contact your Coto Account Manager with any stock inquiries or other questions.