



Product Change Notification

TE Connectivity

Product Change Notification: P-24-026995

PCN Date: 07-OCT-24

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:

Multiple Parts Numbers

Description of Changes

This is a notification only, that our current shipping location will change From: TE Connectivity Corporation TE Pennsylvania DC 1311 S Market St Mechanicsburg PA 17055, USA To: TE Connectivity Corporation El Paso Distribution Center 1740 Joe Battle Blvd. Bldg 3 El Paso TX 79936 USA No Fit/Form/Function Changes No manufacturing location change would be related to this notification No materials change related to this notification

Reason for Changes:

Document clarification.This is a project that will help us to consolidate Products and shipments, which will help to optimize our customer's supply of materials. This consolidation will allow us to focus more resources to secure shipments to our customers.

Estimated Dates:

Last Order Date (Obsolete Parts Only):

First Date To Ship (Changed Parts Only):

13-DEC-2024

Last Ship Date (Obsolete Parts Only):

Last Date for Mixed Shipments: (Changed Parts Only):

No Mixed Shipments

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
063725P022	NO			"6-1190481-1", "ES2000-NO.2-B9-0-STK", "ES2000-2-4FOOT"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
121397P024	NO			"4-1190883-3", "ES2000-NO.3-B8-0-STK"			
130599P006	NO			"6-1190948-4", "ES2000-NO.4-B7-0-STK"			
130599P007	NO			"6-1190948-5", "ES2000-NO.4-B7-0-60MM"			
2056350005	NO			"3-1191490-3", "ES-CAP-NO.3-B8-0-40MM"			
2056350007	NO			"3-1191490-4", "ES-CAP-NO.3-B8-0-50MM"			
206247P038	NO			"2-1191495-7", "SCT-NO.4-E2-0-STK"			
2525596002	NO			"5-1191848-0", "RBK-ILS-125-NR1-0-50MM"			
3371890003	NO			"7-1192545-9", "ES-CAP-NO.1-C1-0-35MM"			
3371890007	NO			"8-1192545-1", "ES-CAP-NO.1-C1-0-50MM"			
5428154001	NO			"4-1194256-8", "LSTT-19-0-SP"			
5510320002	NO			"3-1194355-8", "PD-CAP-1/8-0"			
5628374001	NO			"9-1194446-7", "LSTT-32-0-SP"			
607381P039	NO			"4-1194804-6", "SCT-NO.2-E5-0-50MM"			
7251716003	NO			"TSAS-NR504-X-15MM", "4-1899165-6"			
829131P019	NO			"7-1196474-7", "ES2000-NO.1-C1-0-27MM"			
829131P021	NO			"7-1196474-9", "ES2000-NO.1-C1-0-STK"			
NB20274001	NO						

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
130599P007	NO			"6-1190948-5", "ES2000-NO.4-B7-0-60MM"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
130599P007	NO			"6-1190948-5", "ES2000-NO.4-B7-0-60MM"			
2056350005	NO			"3-1191490-3", "ES-CAP-NO.3-B8-0-40MM"			
2525596002	NO			"5-1191848-0", "RBK-ILS-125-NR1-0-50MM"			
3371890007	NO			"8-1192545-1", "ES-CAP-NO.1-C1-0-50MM"			
5428154001	NO			"4-1194256-8", "LSTT-19-0-SP"			
5628374001	NO			"9-1194446-7", "LSTT-32-0-SP"			
7251716003	NO			"TSAS-NR504-X-15MM", "4-1899165-6"			
NB20274001	NO						

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
130599P007	NO			"6-1190948-5", "ES2000-NO.4-B7-0-60MM"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
063725P022	NO			"6-1190481-1", "ES2000-NO.2-B9-0-STK", "ES2000-2-4FOOT"			
130599P006	NO			"6-1190948-4", "ES2000-NO.4-B7-0-STK"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
121397P024	NO			"4-1190883-3", "ES2000-NO.3-B8-0-STK"			
206247P038	NO			"2-1191495-7", "SCT-NO.4-E2-0-STK"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
063725P022	NO			"6-1190481-1", "ES2000-NO.2-B9-0-STK", "ES2000-2-4FOOT"			
121397P024	NO			"4-1190883-3", "ES2000-NO.3-B8-0-STK"			
130599P006	NO			"6-1190948-4", "ES2000-NO.4-B7-0-STK"			
2056350007	NO			"3-1191490-4", "ES-CAP-NO.3-B8-0-50MM"			
206247P038	NO			"2-1191495-7", "SCT-NO.4-E2-0-STK"			
3371890003	NO			"7-1192545-9", "ES-CAP-NO.1-C1-0-35MM"			
5510320002	NO			"3-1194355-8", "PD-CAP-1/8-0"			
607381P039	NO			"4-1194804-6", "SCT-NO.2-E5-0-50MM"			
829131P019	NO			"7-1196474-7", "ES2000-NO.1-C1-0-27MM"			
829131P021	NO			"7-1196474-9", "ES2000-NO.1-C1-0-STK"			
NB20274001	NO						

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
063725P022	NO			"6-1190481-1", "ES2000-NO.2-B9-0-STK", "ES2000-2-4FOOT"			
121397P024	NO			"4-1190883-3", "ES2000-NO.3-B8-0-STK"			
130599P006	NO			"6-1190948-4", "ES2000-NO.4-B7-0-STK"			
2056350007	NO			"3-1191490-4", "ES-CAP-NO.3-B8-0-50MM"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
206247P038	NO			"2-1191495-7", "SCT-NO.4-E2-0-STK"			
3371890003	NO			"7-1192545-9", "ES-CAP-NO.1-C1-0-35MM"			
5510320002	NO			"3-1194355-8", "PD-CAP-1/8-0"			
607381P039	NO			"4-1194804-6", "SCT-NO.2-E5-0-50MM"			
829131P019	NO			"7-1196474-7", "ES2000-NO.1-C1-0-27MM"			
829131P021	NO			"7-1196474-9", "ES2000-NO.1-C1-0-STK"			
NB20274001	NO						

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
130599P007	NO			"6-1190948-5", "ES2000-NO.4-B7-0-60MM"			
2056350005	NO			"3-1191490-3", "ES-CAP-NO.3-B8-0-40MM"			
2525596002	NO			"5-1191848-0", "RBK-ILS-125-NR1-0-50MM"			
3371890007	NO			"8-1192545-1", "ES-CAP-NO.1-C1-0-50MM"			
5428154001	NO			"4-1194256-8", "LSTT-19-0-SP"			
5628374001	NO			"9-1194446-7", "LSTT-32-0-SP"			
7251716003	NO			"TSAS-NR504-X-15MM", "4-1899165-6"			
NB20274001	NO						