



PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1070

Issue Date: 10/18/2024

Parts Affected	R50BG2-4-0045	Old Rev.	E	New Rev.	F
	R50BG2-5-0080		E		F
	R50BG2-F-0160		E		F
	R50RB2-4-0045		E		F
	R50RB2-5-0080		E		F
	R50RB2-F-0160		E		F
	R50RED-4-0030		A		B
	R50RED-5-0080		E		F
	R50RED-F-0120		A		B
	R50RED-V-0025		B		C
	R50RG2-4-0045		E		F
	R50RG2-5-0080		E		F
	R50RGB-F-0160		E		F
	R50RGB-4-0045		E		F
	R50RGB-5-0080		E		F
	R50RGB-F-0160		E		F
	R50YWLW-4-0030		A		B
	R50YWLW-5-0090		A		B
	R50YWLW-F-0120		A		B
	R50YWLW-V-0025		B		C

Change Will Affect:

This change will affect the product specifications.

Description of Change:

The drawings have been updated with accurate dimensions of the products.

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at www.bivar.com/contact or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1070

Issue Date: 10/18/2024

Effective Date of Change: October 18, 2024

Reason for Change: Typographical error in the datasheets.

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at www.bivar.com/contact or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122